





Important: Keep the (----) area free from paint (overspray in particular).

————— mech. polished
 - . - . - . - main coating surface
 — . . — secondary coating surface

Inventor