

The left part of the drawing shows a side view of a machine. A roller assembly is mounted on a frame. The roller has a series of pins or sensors along its length. The right part of the drawing is a schematic diagram of the roller assembly. It consists of a grid of points labeled A1, A2, A3, A4, F1, and F2. A horizontal arrow labeled 'Durchlauf-richtung' (direction of travel) points to the right. Below the grid is a diagram of the roller assembly, showing a series of pins numbered 1 through 14. The pins are arranged in two rows: the top row has pins 14, 13, 12, 11, 10, and 9; the bottom row has pins 8, 7, 6, 5, 4, 3, 2, and 1. The pins are connected by lines, forming a continuous path. A legend indicates that a solid dot represents an 'Andruckwalze' (pressure roller). Below the diagram, it is noted that positions 8 and 14 are only present in Isomat 4.

					Stck. Qty.		Art.-Nr. Zubehör Art.-No. Accessories	
	Stck. Qty.	Art.-Nr. Art.-No. für Isomat 5	Art.-Nr. Art.-No. für Isomat 4	Bestückungsfolge (v. innen nach außen) Assembly sequence (inside to outside)				
A1	1	280736 B	280736 B	R1/S1/R3/A1/R3/R4/S1	R1	5	296209	(6.5 mm)
A2	1	280736 B	280736 B	R1/R2/A2/R5	R2	3	280748	(6.0 mm)
A3	1	280737 B	280736 B	R1/S1/R3/A3/R3/R4/S1	R3	4	296449	(2.0 mm)
A4	1	280737 B	280736 B	R1/R2/A4/R5	R4	2	283316	(19.5 mm)
F1	1	280738 B		R1/R2/F1/R5	R5	3	296229	(5.5 mm)
F2	1	283165			S1	4	282014	(Scheibe)