


A schematic diagram of a mechanical testing machine. It features a base with a specimen mounted on it. A testing head is positioned above the specimen, with a handle attached to it. The handle is shown in a position where it can be moved to apply tension to the specimen. The diagram illustrates the components and the setup for a tensile test.



	Stck. Qty.	Art.-Nr. Art.-No. für Isomat 3/5	Art.-Nr. Art.-No. für Isomat 4	Bestückungsfolge (v. innen nach außen) Assembly sequence (inside to outside)	R1	Stck. Qty. 6	Art.-Nr. Zubehör Art.-No. Accessories 280750 (Adapter)
A1	1	282615 A	282615 A	R1/A1			
A2	1	282615 A	282615 A	R1/A2			
A3	1	282616 A	282615 A	R1/A3			
A4	1	282616 A	282615 A	R1/A4			
F1	1	282617 A		R1/F1			
F2	1	282617 A		R1/F2			
		Zulässige Abweichung Permissible tolerance	Oberflächenabwicklung Circumference	VP PU	Info-Plan:		
			mech. polished —	Maßstab Scale 1 : 1	Gewicht Weight g/m		
			uml. total				
Paßmaße Close tol.		Abmaße Std. tolerance	beschichtet coated — — —	Werkstoff Material			
Original / Änderung Revision / Version 0100		Datum Date 12.09.2006	Name finkca	Benennung Title Rollenplan Isomat 3/4/5	IsoModul		
Name		gez. drawn Finkemeyer	gepr. checked Winkler	Schüco ADS 70.HI			
		ges. seen Nienhäuser					
		SCHÜCO		Zeichn.-Nr. Drawing No. 393110 RP 1000			
				EDV erstellt Ohne Unterschrift gültig generated by EDP valid without signature	Ersatz für Replacement for		